

# KNX Humidity and Temperature sensor for flush mounting

ZSFSENV2 TECHNICAL DOCUMENTATION

#### **FEATURES**

- Indoor temperature and relative humidity measurement
- Temperature, relative humidity and condensation alarms
- Dew point temperature measurement
- · Relative humidity notification through color LED
- Logic functions
- 2 inputs configurable as binary input, temperature probe or motion detector
- Total data saving on KNX bus failure
- Integrated KNX BCU (TP1-256)
- Available in the following colors: silver (RAL 9006), anthracite black (RAL 9004), white (RAL 9016) and gloss white (RAL 9003)
- Dimensions 82 x 82 x 33.2 mm
- Flush mount on back box
- Conformity with the CE, UKCA, RCM directives (marks on the back side)




Figure 1: Flat Sensato v2

1. Humidity notification LED2. KNX connector3. Inputs connector4. Programming Button5. Programming LED6. Temperature and humidity sensor with protection membrane

Programming button: short press to set programming mode. If this button is held while plugging the device into the KNX bus, it enters the safe mode.

Programming LED: programming mode indicator (red). When the device enters the safe mode, it blinks (red) every half second. During the start-up (reset or after KNX bus failure) and if the device is not in safe mode, it emits a red flash.

GENERAL :	SPECIFICATION	ONS			
CONCEPT			DESCRIPTION		
Type of device			Electric operation control device		
KNX supply	Voltage (typical)		29 VDC SELV		
	Voltage range		21-31 VDC		
	Maximum consumption	Voltage	mA	mW	
		29 VDC (typical)	4.1	118.9	
	consumption	24 VDC <sup>1</sup>	10	240	
	Connection type		Typical TP1 bus connector for 0.8 mm Ø rigid cable		
External pow	er supply		Not required	Not required	
Operation ten	nperature		0 +55 °C		
Storage temp	erature		-20 +55 °C	-20 +55 °C	
Operation humidity			5 95%		
Storage humi	idity		5 95%		
Complementary characteristics			Class B		
Protection class			III	III	
Operation type			Continuous operation	Continuous operation	
Device action type			Type 1	Type 1	
Electrical stress period			Long		
Degree of protection			IP20, clean environment		
Installation			Flush mount on back box	Flush mount on back box	
Minimum clearances			Not required		
Response on KNX bus failure			Data saving according to parameterization		
Response on	KNX bus restar	t	Data recovery according to parameterization		
			The programming LED indicates programming mode (red). The humidity		
Operation indicator			notification LED can be parameterized to notify the measurement of comfort,		
			extreme or very extreme relative humidity levels by means of a green, yellow		
			or red light, respectively.		
Weight			78 g		
Housing mate		est anno anno ein (IANV Fo	PC+ABS FR V0 halogen free		

<sup>&</sup>lt;sup>1</sup> Maximum consumption in the worst-case scenario (KNX Fan-In model).


INTEGRATED HUMIDITY AND TEMPERATURE SENSOR SPECIFICATIONS				
CONCEPT	DESCRIPTION			
Temperature measurement range	0 90 °C			
Temperature resolution / accuracy	0.1 °C / ±0.5 °C (@ 25 °C)			
Humidity measurement range	0 100% RH			
Humidity response time	1 s			
Humidity resolution / accuracy	1% / ±3% RH			
Humidity drift	±0.25% RH per year in normal air			

INPUTS SPECIFICATIONS AND CONNECTIONS			
CONCEPT	DESCRIPTION		
Number of inputs	2		
Inputs per common	2		
Operation voltage	+3.3 VDC in the common		
Operation current	1 mA @ 3.3 VDC (per input)		
Switching type	Dry voltage contacts between input and common		
Connection method	Pluggable screw terminal block (0.2 Nm max.)		
Cable cross-section	0.2-1.5 mm <sup>2</sup> (IEC) / 28-14 AWG (UL)		
Maximum cable length	30 m		
NTC accuracy (@ 25 °C) <sup>2</sup>	±0.5 °C		
Temperature resolution	0.1 °C		
Maximum response time	10 ms		

<sup>&</sup>lt;sup>2</sup> For Zennio temperature probes.

### INPUTS CONNECTION

Any combination of the following accessories is allowed in the inputs:



Switch/Sensor/ **Push button** 




must not be connected together.


- \* In case of using ZN1IO-DETEC-P sensor, its micro switch number 2 must be in Type B position.
- \*\* Zennio temperature probe or any NTC with known resistance values at three points in the range [-55, 150 °C].

#### INSTALLATION INSTRUCTIONS

# <u> MPORTANT</u>:

- 1. The flush-mounted box must be completely sealed once the cables are inside. Airtight boxes, polyurethane foam, silicone rubber or similar nonbreathable construction materials can be used.
- 2. The mounting location must not be exposed to airflows or direct sun radiation.







# SAFETY INSTRUCTIONS AND ADDITIONAL NOTES

- · Installation should only be performed by qualified professionals according to the laws and regulations applicable in each country.
- Do not connect the mains voltage nor any other external voltage to any point of the KNX bus, it would represent a risk for the entire KNX system. The facility must have enough insulation between the mains (or auxiliary) voltage and the KNX bus or the wires of other accessories, in case of being installed.
- Keep the device away from water (condensation over the device included) and do not cover it with clothes, paper or any other material while in use.
- The WEEE logo means that this device contains electronic parts and it must be properly disposed of by following the instructions at https://www.zennio.com/en/legal/weee-regulation.
- This device contains software subject to specific licences. For details, please refer to https://zennio.com/licenses.

2